Existing Site Photographs

This document contains existing site photographs to support the planning application for the conversion of the detached garage to a bungalow at 659 Altrincham Road, Baguley, Manchester, M23 9AA. The photos illustrate the current condition of the property, including damage to the front elevation, fencing, and windows caused by a vehicle collision. They provide context for the proposed works and demonstrate how the scheme will improve the appearance and curtilage of the site.



Caption: Front Elevation – Existing Condition (showing accident damage)



Caption: Side Elevation – Existing Condition



Caption: Garage and Driveway – Existing Condition



Caption: Street Scene – Context View