



Whalley Range - Footpath Photographs

135-141 Withington Road,
Whalley Range,
Manchester,
M16 8EE

Date:

31/07/2025

Front Elevation Footpath (Withington Road)



Existing front elevation pavement exhibits extensive cracking throughout its surface, indicating significant wear and structural deterioration. The overall condition suggests prolonged exposure to stress, weathering, or possible sub-base failure.

Side Elevation Footpath (Mayfield Road)



Existing side elevation pavement exhibits extensive cracking throughout its surface, indicating significant wear and structural deterioration. The overall condition suggests prolonged exposure to stress, weathering, or possible sub-base failure.

Side Elevation Car Park Entrance (Mayfield Road)



Existing Car park shows cracking and damaged tar mac surface resulting in pot holes.