
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 13

Defect Survey

Defect Survey Sheet




Notes:


Any marks not numbered are not part of Zone 13. Number 29 is a large repair with steel inside.

Photo References







3


4


5



6


7



8


9


10
11


12
13
14


16


15


17


18


19


20


21


22


23


24


25


26


44


45


46


27


28


29



30


31


32


33


34



36


35


37



38


39


40


41


42


43