
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 1

Defect Survey

Defect Survey



Notes


Numbers 27, 28, 29 are three blocks with lots of repairs and what looks where are sign or something else has been placed previously on the face of the building.

CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Photo References













7


8


9


10


11



12


13


14



15


16


17


18



19



20


21


22


23


24


25


26


27


28


29


30
31


32


33


34


35


36


37


38



39


40


41


42


43


45
46
44



47


48


49


50


51


52


53


54


55


56