RSA Designers Response

ROAD SAFETY AUDIT STAGE 1/2

Project Title	Portugal Street – S278 Works
Client	Olympian Homes
Curtins Job Ref No:	080851
RSA Response Ref:	080851-CUR-00-XX-RP-001-V01 S278 Highway Works - RSA 1-2 Designer Response
Road Safety Report Ref:	610/2024/118/01 Rev 1

Problem Identified (Paragraph No)	**Problem Accepted** (YES/NO)	**Recommendation Accepted** (YES/NO)	**Comments** (describe)
2.2.1	N	Y	Refuse vehicle and fire appliance have been tracked with the largest shown below. It demonstrates that there is no encroachment onto the footway by either vehicle. Any service vehicles will use the service entrance which is on the right-hand side before the cul-de-sac and they will exit the service entrance in the same location but turning left out. 
2.4.1	Y	Y	The drawing pack has been updated to include this crossing with dropped kerbs and tactile paving.

Signed	[redacted]	[redacted]
Name	Richard Bartlett	Andy Rain
Job Title	Principal Engineer	Head of Infrastructure
Date	02.04.2024	02.04.2024