

TRINITY SITE D - CONDITION 180 - HABITAT BOXES

REV	PURPOSE OF ISSUE	DATE	AUTHOR
REV (-)	FIRST ISSUE	27/08/2025	KATY HAYHOE

S Q U A R E Y A R D

Tel. > +44 (0) 7514 281 452
Email. > studio@yd2.co.uk
Web. > www.yd2.co.uk

S Q U A R E Y A R D

ECOLOGY REQUIREMENTS

BAT BOXES



The ecology report requires:

2 x Bat Boxes *

Located in a un-lit part of the site with close proximity to the river for foraging and close to the underside of the bridge. Located circa 4m high above the ground.



Schwegler Bat Winter Roost 1WQ

BIRD BOXES



The ecology report requires:

2 x Swift Boxes
2 x General Bird Boxes *
1 x Black Red Start Boxes


Located to avoid vent locations and to be north facing and circa 2.5m above the paving level and 2m above the planting level.




Woodstone® Swift façade nest box



WoodStone® External House Sparrow Nest Box (suitable for general birds)



Schwegler 1HE Open Fronted Brick Box With Bracket (suitable for Black Red Starts)



Indicative bird box location
Sat beneath the coping stone and aligned centrally to the cladding panels

