

Purified Air Limited

Lyon House
Lyon Road
Romford
Essex
RM1 2BG



Tel: +44 1708 755414
Fax: +44 1708 721488
E-Mail: enq@purifiedair.com
Web Site: www.purifiedair.com

ADDITIONAL COMMISSIONING INFORMATION

Equip No:		Inspect No:	78713
Make/Model:		Job No:	214281
Serial No:		Contact:	
Cust Equip No:		Inspected:	06/05/2025
Meter:		Printed:	08/05/2025
		Page: 1 of 1	

Site:
Big Mamma Manchester
ST MICHAELS BUILDING
38 JACKSON ROW
Manchester
M2 5WD

Items to Inspect	Result	Comments
ADDITIONAL COMMISSIONING INFORMATION		
Access to Kit, do we need any additional access like ladders (Stairs, Lift, Hatch)	Please Give Details	Stairs
Access to Unit (Walk in, Loading Bay)	Please Give Details	Walk in
Any Health & Safety Issues	Please Give Details	No
Any other equipment fitted (not our kit)	Please Give Details	No
Any other restaurants near by that could cause nuisance (Smell)	Please Give Details	No
Any other restaurants nearby that we look after	Please Give Details	No
Any weather issues (Too cold than no access to roof etc..)	Please Give Details	No
Are keys available	Yes	
Can it be serviced by One Person	No	
Location of Kit (Internal, Suspended Ceiling)	Please Give Details	Suspended ceiling
Location of the Unit	Please Give Details	Suspended ceiling
Parking (Multi Storey, Street Bays)	Please Give Details	Loading bay
Parking Restrictions (Permits required, Times)	Please Give Details	Yes
Restaurant operating hours	Please Give Details	N/A

Items to Inspect	Result	Comments
ADDITIONAL COMMISSIONING INFORMATION		
Servicing Requirements (Notice needed, booking required?)	Please Give Details	Booking

Service carried out by:

Engineer Name: Carl Birchall

Signature:

Customer Name: Customer Not Present

Signature:



ESP Commissioning Report

Equip No:		Inspect No:	78714
Make/Model:		Job No:	214281
Serial No:		Contact:	
Cust Equip No:		Inspected:	06/05/2025
Meter:		Printed:	08/05/2025
		Page: 1 of 1	

Site:	Big Mamma Manchester ST MICHAELS BUILDING 38 JACKSON ROW Manchester M2 5WD
--------------	--

Items to Inspect	Result	Comments
ESP COMMISSIONING REPORT		
Details of Access equipment needed for service (Ladder, Tower)	-	Ladders
Access for future maintenance	Good/Poor - Please Comment	Good
Air Flow Direction checked	Yes	
Charge rate to collector	Please Give Details	Yes
Charge rate to ioniser	Please Give Details	Yes
Collector cells checked and free from damage	Yes	
Collector cells fitted correctly	Yes	
Door Safety switch checked	Yes	
Drain plug in place	Yes	
ESP Interlocked with fan so that unit switches off when fan not running	Pass	
ESP unit wired to to mains power	Yes	
Indicator light functioning	Yes	
Mesh Filter fitted front & back	Yes	

Service carried out by: [Signature] Engineer Name: Carl Birchall
 Customer Name: Customer Not Present
 Signature:

Purified Air Limited

Lyon House
Lyon Road
Romford
Essex
RM1 2BG



Tel: +44 1708 755414
Fax: +44 1708 721488
E-Mail: enq@purifiedair.com
Web Site: www.purifiedair.com

ADDITIONAL COMMISSIONING INFORMATION

Equip No:		Inspect No:	78713
Make/Model:		Job No:	214281
Serial No:		Contact:	
Cust Equip No:		Inspected:	06/05/2025
Meter:		Printed:	08/05/2025
		Page: 1 of 1	
Site:		Big Mamma Manchester ST MICHAELS BUILDING 38 JACKSON ROW Manchester M2 5WD	

Items to Inspect	Result	Comments
ADDITIONAL COMMISSIONING INFORMATION		
Access to Kit, do we need any additional access like ladders (Stairs, Lift, Hatch)	Please Give Details	Stairs
Access to Unit (Walk in, Loading Bay)	Please Give Details	Walk in
Any Health & Safety Issues	Please Give Details	No
Any other equipment fitted (not our kit)	Please Give Details	No
Any other restaurants near by that could cause nuisance (Smell)	Please Give Details	No
Any other restaurants nearby that we look after	Please Give Details	No
Any weather issues (Too cold than no access to roof etc..)	Please Give Details	No
Are keys available	Yes	
Can it be serviced by One Person	No	
Location of Kit (Internal, Suspended Ceiling)	Please Give Details	Suspended ceiling
Location of the Unit	Please Give Details	Suspended ceiling
Parking (Multi Storey, Street Bays)	Please Give Details	Loading bay
Parking Restrictions (Permits required, Times)	Please Give Details	Yes
Restaurant operating hours	Please Give Details	N/A

Items to Inspect	Result	Comments
ADDITIONAL COMMISSIONING INFORMATION		
Servicing Requirements (Notice needed, booking required?)	Please Give Details	Booking

Service carried out by:

Engineer Name: Carl Birchall

Signature:

Customer Name: Customer Not Present

Signature:



ESP Commissioning Report

Equip No:		Inspect No:	78714
Make/Model:		Job No:	214281
Serial No:		Contact:	
Cust Equip No:		Inspected:	06/05/2025
Meter:		Printed:	08/05/2025
		Page: 1 of 1	

Site:
 Big Mamma Manchester
 ST MICHAELS BUILDING
 38 JACKSON ROW
 Manchester
 M2 5WD

Items to Inspect	Result	Comments
ESP COMMISSIONING REPORT		
Details of Access equipment needed for service (Ladder, Tower)	-	Ladders
Access for future maintenance	Good/Poor - Please Comment	Good
Air Flow Direction checked	Yes	
Charge rate to collector	Please Give Details	Yes
Charge rate to ioniser	Please Give Details	Yes
Collector cells checked and free from damage	Yes	
Collector cells fitted correctly	Yes	
Door Safety switch checked	Yes	
Drain plug in place	Yes	
ESP Interlocked with fan so that unit switches off when fan not running	Pass	
ESP unit wired to to mains power	Yes	
Indicator light functioning	Yes	
Mesh Filter fitted front & back	Yes	

Service carried out by: Engineer Name: Carl Birchall

Signature:

Customer Name: Customer Not Present

Signature: