NEWALL GREEN DRAINAGE SURVEY

13839

Thursday, 01 May 2025

14 Observations

Andy Thomas

Marston & Grundy LLP

Marston & Grundy LLP
Consulting Engineers



Observation 1

Location: MH SW17a

MH clear



Observation 2

Location: MH SW17b

MH clear



Observation 3

Location: MH SW18

MH clear



Observation 4

Location: MH SW19

Hydrobrake visible and MH cleaf



Observation 5

Location: MH CW01

Downstream pipeline to MH7201 clear.
Upstream to SW19 clear.
Upstream to FW 21clear.



Observation 6

Location: MH FW14

Upstream to FW9 clear
Upstream to FW13 required jetting.
Downstream to FW21 clear



Observation 7

Location: FW21

Downstream to CW01 clear.
Upstream pipe required jetting.



Observation 8

Location: UU MH 7201

Downstream sewer clear



Observation 9

Location: UUMH 7201



Observation 10

Location: MH No Reference

Lateral from residential



Observation 11

Location: UU MH 8203

Located in garden, no access at time of visit



Observation 12

Location: UUMH Upstream Of 8203



Observation 13

Location: UUMH Upstream Of 8203



Observation 14

Location: UUMH Upstream Of 8203