

Client **Portland street**
Job **Sample window for conservation drawing**
Ref **2nd floor (3 along from stairs) Front Elevation**

**1 X Sliding Sash - SS1 (Portland Street Restoration - Refurb existing sashes.
Removal of existing glass and re-installation of 12mm Heritage glass)**



