


Dennis NEEDA.
16 Demesne Rd.
M16 8HG.

T1-T22.

Road at corners that have been
butchered down to 7th and left.
destroyed the fence, post, which boards.
Too close to house, remove and grind
and install brand new fence.

T23, Holly tree, very messy, self seeded.
fight next to house Bay window,
Survey shows that the structure has
movement, remove Holly and grind.
Check for rats in drains and
foundations.

DNH01



Demesne Rd.