United Utilities Inspection Sheet
Development CCTV Work
(Manholes and gravity sewers)

United Utilities
Water for the North West

Site name:	Harry Dalton, Chorlton Manchester
Site address	Harry Dalton, Chorlton Manchester
District Council:	Trafford
United Utilities Notification number	3990268

Accurate 'as built' drawing received?	Please select
Development achieved 50% occupancy?	Please select
Type of remedial list:	Please select

DSI Contact name:	Marcus Jones	Telephone:	
		Email:	
Adoptions Engineer:		Telephone:	
		Email:	
Developer: Contact name:		Telephone:	
		Email:	
Contractor: Contact name:		Telephone:	
		Email:	

Please note a final inspection cannot be completed until the development is completed and has a minimum of 50% occupancy. Where the status 'observation feedback during construction' is used, this is not the final inspection. Additional actions may arise upon completion of the final inspection.

SEWER REMEDIAL WORK

MH TO MH	Status	Approx. meterage	Defect observed	Action(s)
F6-F3	Passed	8		
F6-F7	Passed	23.08		
F7-F8	Passed	19.68		
F8-F9	Passed	24.86		
F1-F2	Passed	52.42		
F2-F3	Passed	75.77		
F4-F5	Passed	62.85		
F5-F6	Passed - Actions listed confirmed as completed	19.5	Back fall observed within line of sewer	
S1-S2	Passed	19.6		
S2-S3	Passed	8.25		
S3-S4	Passed	55.13		
S4-S5	Passed	70.15		
S6-S7	Passed	57.49		
S7-S8	Passed	57.74		
S8-S9	Passed	37.14		

Add new row(s)

You may wish to refer to United Utilities website for Developer Services. This can be found using the following link:
https://www.unitedutilities.com/builders-developers/wastewater-services-and-connections/

Additional comments:

Issued by:	*Marcus Jones*	Date of Inspection:	25/03/2025

Convert To PDF & Save

Email Job Pack

Use for submitting CCTV **ONLY**

Sends to DSI Job Pack Mailbox