

JH.A
PHOTOGRAPH
SURVEY

PHOTOGRAPH SURVEY
21 MANOR STREET
MANCHESTER
M12 6HE

21 MANOR
STREET



EXTERIOR



REF 1: EXISTING PARKING SPOTS TO THE FRONT OF THE PROPERTY



REF 2: FRONT ELEVATION OF THE PROPERTY




REF 3: REAR ACCESS TO THE PROPERTY



REF 4: ENCLOSED REAR YARD WITH ACCESS TO THE BASEMENT LEVELS



REF 5: ACCESS TO EXISTING BASEMENT LEVEL



REF 6: EXISTING WASTE COLLECTION ROUTE RETAINED


INTERIOR




REF 7: CENTRAL STAIRCASE WITHIN THE PROPERTY



REF 8: SECOND FLOOR INTERIOR ROOM FINISHES



REF 9: FIRST FLOOR CIRCULATION AREA



REF 10: MAIN ENTRANCE LOBBY



REF 11: FIRST FLOOR WINDOW CONDITION



REF 12: FIRST FLOOR INTERIOR

INTERIOR



REF 13: FIRST FLOOR REAR SASH WINDOWS



REF 14: FIRST FLOOR FRONT WINDOWS



REF 15: STAIRCASE TO SECOND FLOOR



REF 16: BASEMENT WINDOWS




REF 17: BASEMENT VAULTED CEILING SHOWER




REF 18: GROUND FLOOR ROOM LOOKING TOWARDS THE REAR OF THE PROPERTY

PLANS




Basement Plan
Scale @ 1:50




Ground Floor Plan
Scale @ 1:50

PLANS



First Floor Plan
Scale @ 1:50



Second Floor Plan
Scale @ 1:50