

9 Telford Court, Dunkirk Lea, Chester Gates, Chester, CH1 6LT. Tel: 01244 851753 Fax: 01244 851752

Access this document online via your asbestos management portal: www.apecuk.org/data

Site Air Test Certificate Ref:	ST/23/7/27/AA2	Date of Issue:	27/07/2023	Page 1 of 4
--------------------------------	----------------	----------------	------------	-------------

Note: Inspection undertaken in accordance with APEC in-house Methods QCRF2, OH1 and OH2, based on the HSE publication HSG 248 'The Analysts Guide'

Site: 87 Rochdale Road Manchester M4 4HY	Client: Chartrange Chartrange Wharf Street Dukinfield Cheshire SK16 4NJ	Contractor: Chartrange Chartrange Wharf Street Dukinfield Cheshire SK16 4NJ
Contact: NA	Contact: James Kennedy	Contact: N/A

Samples taken by (APEC)


Analyst	Andy Alker	Signed by (APEC)		Date	27/07/2023
----------------	------------	-------------------------	---	-------------	------------

Air Testing

Purpose of Test

Far-Source Sampling	☒	Near-Source sampling	☐	Leak Test	☐	Background Test	☐	Reassurance Test	☐
----------------------------	-------------------------------------	-----------------------------	--------------------------	------------------	--------------------------	------------------------	--------------------------	-------------------------	--------------------------

Site Photograph and Additional Site Information

	Area Assessed:	Western edge of Construction site towards high-rise apartments		
	Description of reason for test (including the nature and extent of ACMs removed):	Far source monitoring to small area of contaminated land on the construction site is being excavated		
	Site Specific Risk Assessment:	Project Information Sheet (if used):		
	RA/23/7/27/AA2	NA		

Sample Area Layout Plan



9 Telford Court, Dunkirk Lea, Chester Gates, Chester, CH1 6LT. Tel: 01244 851753 Fax: 01244 851752

Access this document online via your asbestos management portal: www.apecuk.org/data

Site Air Test Certificate Ref:

ST/23/7/27/AA2

Date of Issue:

27/07/2023

Page 3 of 4

Photographs

Contaminated Area To be Excavated



Contaminated Area To be Excavated



Contaminated Area To be Excavated



Photograph 4

Sampling pump (sample ref: 23/7/A/27/AA4)



Sampling pump (sample ref: 23/7/A/27/AA5)



