
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 14

Cover Meter Survey

Visual OD's and Cover Survey





Notes

30, 31, 32, 33 are a group of bolts over all four blocks. 35 is a continuous bed running horizontally across the elevation. The corner with Chancery Lane is continuous all the way up that side of the elevation.

Photo References














8


9



15
14
13
12
11


21
20
19
18
17
16


22


23


24


25


26


28
27


29


32
33
31
30


35


36



38


37


39



40


41


46
45
44
43
42


47


48


49



50


51


52


53


54


60
59
58
57
56
55


61