

# Certificate of Cleanliness (Non-Licensed Works)



Northstar  
Environmental  
Ltd  
Compass House  
Bank Farm  
Ledsham La  
Ellesmere Port  
CH66 0NA  
0151 538 3141

Email: [info@northstarenvironmental.co.uk](mailto:info@northstarenvironmental.co.uk) Website: [www.northstarenvironmental.co.uk](http://www.northstarenvironmental.co.uk)

Certificate No:

J092270/EV02

Date:

06 Jun  
2023



Tests carried out in accordance with North Star Environmental in-house Technical Procedures NSDOC48 & HSE Guidance HSG 248:2021  
All four stages of the clearance procedure, air sampling & fibre counting have been accredited by UKAS

| Client                                                                                       | Removal Contractor                                                                      | Site Address                                                       | Description of Work Area & Works Carried Out                                                                                                      |
|----------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| ARD Industrials Services LTD<br>Unit 1<br>Saxon Street<br>Middleton<br>Manchester<br>M24 2AD | ARD Industrials Services LTD<br>Unit 1, Saxon Street, Middleton,<br>Manchester, M24 2AD | St. Lukes Social Club<br>Sulby Street<br>Manchester<br><br>M40 5HR | Visual inspection following the litter pick of ACM's from fire damaged building which contained asbestos.<br><br>Former Social Club - Boiler Room |
| <b>Contact:</b> Adam Roche                                                                   | <b>Contact:</b> Adam Roche                                                              | <b>Supervisor:</b>                                                 | Jamie Pomfret                                                                                                                                     |

|                                                                                                     |            |                                            |              |
|-----------------------------------------------------------------------------------------------------|------------|--------------------------------------------|--------------|
| All ACM's outlined within scope of works have been completely removed from the under lying surfaces | <b>Yes</b> | Has air testing been carried out?          | <b>Yes</b>   |
| Work area is free from debris and fine settled dust                                                 | <b>Yes</b> | If yes, Air test Certificate Reference No: | J092270/EV01 |

Comments:

John Webb demolition have excavated down to the agreed level. All material generated was removed as contaminated waste. Visual inspection to former boiler room and surrounding areas, no visible quantifiable asbestos debris were present at this time.

Following visual inspection, I am satisfied that the area is clean and can be returned to normal use

|                     |               |                   |  |              |             |
|---------------------|---------------|-------------------|--|--------------|-------------|
| <b>Assessed By:</b> | Mark Richards | <b>Signature:</b> |  | <b>Date:</b> | 06 Jun 2023 |
| <b>Supervisor:</b>  | Jamie Pomfret | <b>Signature:</b> |  | <b>Date:</b> | 06 Jun 2023 |

This certificate is invalid unless signed by an authorised analyst of North Star Environmental Ltd. Any queries as to the authenticity of this certificate can be clarified by contacting North Star office at the above address. It should be noted that any opinions or interpretations detailed herein are outside the scope of UKAS testing accreditation held.

| Photographs                                                                      |                                                                                   |                                                                                    |                                                                                     |
|----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |  |  |
| Forward Boiler Room                                                              | Former Boiler Room                                                                | Former Boiler Room                                                                 | Former Boiler Room                                                                  |
|  |  |  |  |
| Surrounding Areas                                                                | Surrounding Areas                                                                 | Surrounding Areas                                                                  | Former Social Club                                                                  |

