





- 1 Carefully remove all existing balustrading around void including all associated elements and components. Allow for making good, consolidation and remediation.
- 2 Carefully remove all temporary wall around void including all associated elements and components. Allow for making good, consolidation and remediation.
- 3 Carefully remove existing floor finishes/coverings to include all separation layers/underlays. Allow for making good consolidation and remediation.

Stair/Lift Lobby

Stair/Lift Lobby

Stair/Lift Lobby



General Notes

The existing general arrangement base drawings (plans, sections and elevations) are based upon 2010 data and in some instances may not reflect the current arrangement.

Dimensions and arrangements must be checked for accuracy on site by contractor prior to any works commencing, ordering or manufacture/fabrication of any elements or components.

Any discrepancies/irregularities must be reported to the CA immediately.

No work shall commence until any such discrepancies have been resolved.

Limitations

The drawings are based upon existing data and no concealed and/or hidden spaces have been exposed and/or opened up for inspection unless specifically highlighted. Therefore, the arrangement and interfacing illustrated across details are purely indicative/approximate only. The accuracy of the survey data graphically presented cannot be confirmed. These drawings are for tender purposes only.

Scale

0.5 0 0.5 1 1.5 2 2.5 m
SCALE 1:50

Legend

— Project Boundary

■ Not in Scope

P01 December 2024 FINAL ISSUE

Rev	Date	Ints	Details
1	16/12/2024 15:30:31		

© The moral rights of the author are hereby asserted.
This drawing and design is the sole property of Buttress Ltd and must not be reproduced without permission.
Buttress Ltd is Registered in England and Wales, 5363573

Buttress

Manchester
41 Bengal Street
Manchester
M4 6AF
0161 236 3303
www.buttress.net

Leeds
Clockwise, Yorkshire House
Greek Street, Leeds
LS1 5SH
0113 539 7965

Certified
Corporation

Project Title SIM CONFERENCE CENTRE
Client SCIENCE MUSEUM GROUP
Location MANCHESTER

Drawing ref Second Floor Demolition & Removals Sections - Sheet 2

Date 16/12/2024 15:30:31 **Scale** As indicated
Checker AS **Size** A1
Job No: 9657 **Status** S4 Suitable for Stage Approval

Project	Origin	Volume	Level	Type	Role	Number	Rev
SMGCON-BUT-SI-XX-DR-A-20003-P01							

2 Existing Section BB
1 : 50