

70 Woodheys Drive
Sale
Cheshire
M33 4JD
Tel: 0161 969 2675



GMI Construction Ltd.

Moss Lane East, Moss Side, Manchester.

Dilapidation Survey.

11th September 2024.

The condition survey was carried out on 11th September 2024 by Paul Hodgson of SightSafe GB Ltd.

The list below is the sequence of how the survey was carried out, the numbering shows the file location followed by the description of the areas, as identified in the drawings below.





1A-1B - Parkfield Street - Kerbs and Footpath
 2A-2B - Parkfield Street - Kerbs and Footpath
 3A-3B - Parkfield Street - Road Surface

4A-4B - Heald Place - Kerbs and Footpath
 5A-5B - Heald Place - Kerbs and Footpath
 6A-6B - Heald Place - Road Surface

7A-7B - Moss Lane East - Kerbs and Footpath
 8A-8B - Moss Lane East - Kerbs and Footpath
 9A-9B - Moss Lane East - Road Surface
 10A-10B - Moss Lane East - Road Surface