


Acoustic Assessment Report

Introduction

This report presents the findings of an acoustic assessment conducted for our new studio unit, L3. The studio is designed primarily for low-intensity exercise activities, such as Pilates, which typically involve the use of light music. The studio is in a building with adjoining corridors, a coffee bar, and a plant room situated above the unit.

Location of studio:


As indicated in red, there is a large plant room containing conditioning machines located above unit L3. As indicated in blue, to the right of the studio is a corridor, which is also very empty.



The corridor image is shown below:



on left side of unit L3 is coffee bar:



As indicated in the above layout, unit L3 is not close to any residential space. Considering the light music that will be used in the studio for Pilates, it is very unlikely to impact residential units.

Continue Monitoring:

We will continue observing and monitoring any issues raised regarding noise.

Conclusion:

Based on the findings of this acoustic assessment, unit L3 is sufficiently isolated from residential spaces, and the light music used for Pilates is unlikely to impact nearby areas. We will continue to monitor for any potential issues.