



Drainage Report

Address: Dalton Avenue, Fallowfield

Drain Survey of Sewer Line:

CCTV works carried out at the above site to establish the drainage run, connection and condition of pipework on the 300mm VC sewer running down the alleyway between Dalton Avenue and Thornton Road.

The sewer appears to be combined and was in good serviceable condition with no issues to report.

The drains ran from the direction of Dalton Avenue, down a rear alleyway past the proposed site and connected into a shared manhole in the alleyway behind the properties on Thornton Road. The sewer then travelled between two blocks of houses and discharged to another sewer on Thornton Road (Red arrows on layout below).





If you require any further information in addition to our outlined findings, please don't hesitate to contact me.

Contact details as below:



0800 024 8494



Info@wmd-group.co.uk



38 Neal Avenue, Heald Green, Stockpot, SK8 3QJ



watermainsanddrains.co.uk