

2F Window Inspection

Window 1

- Operational – No
- Glazing – Not damaged, minor soiling
- Ironmongery – Not operational
- Sash Cords – Fine
- Window Boards / Frame – Minor damage noted

Window 2

- Operational – No
- Glazing – Satisfactory condition
- Ironmongery – Poor condition
- Sash Cords – Satisfactory condition
- Window Boards / Frame – Satisfactory condition

Window 3

- Operational – No
- Glazing – Glazing pane cracked on top pane
- Ironmongery – Poor condition
- Sash Cords – Satisfactory condition
- Window Boards / Frame – Satisfactory condition

Window 4

- Operational – No
- Glazing – Satisfactory condition, minor soiling
- Ironmongery – Poor condition
- Sash Cords – Satisfactory condition
- Window Boards / Frame - Satisfactory condition

Window 5

- Operational – No
- Glazing – Satisfactory condition
- Ironmongery – Poor condition
- Sash Cords – Right hand side sash cord broken
- Window Boards / Frame – Minor damage noted

Window 6

- Operational – Yes
- Glazing – No damage noted
- Ironmongery – Poor condition
- Sash Cords – Satisfactory condition / operational
- Window Boards / Frame – Minor damage noted

Window 7

- Operational – Yes
- Glazing – No damage noted
- Ironmongery – Poor condition
- Sash Cords – Operational
- Window Boards / Frame – Poor condition, damage noted to the window board

Window 8

- Operational – Yes
- Glazing – No damage noted
- Ironmongery – Poor condition
- Sash Cords – Operational
- Window Boards / Frame – Severe damage noted to the frame and window board

Window 9

- Operational – No
- Glazing – Cracked pane bottom unit
- Ironmongery – Not operational
- Sash Cords – Fine
- Window Boards / Frame – Satisfactory condition

Window 10

- Operational – No
- Glazing – No damage noted
- Ironmongery – Not operational
- Sash Cords – LHS sash cord broken
- Window Boards / Frame – Satisfactory condition

Window 11

- Operational – No
- Glazing – No damage noted
- Ironmongery – Poor condition
- Sash Cords – Satisfactory condition
- Window Boards / Frame – Minor damage noted