

Photograph 1**Date:** 31/10/2024**Description:**

BH201 position.

**Photograph 2****Date:** 31/10/2024**Description:**Metal recovered
at 1.80m bgl in
BH201.

Photograph 3		
Date: 31/10/2024		
Description: BH201 -Made Ground arisings to 1.80m bgl.		
Photograph 4		
Date: 31/10/2024		
Description: BH201 - clay arisings from 1.80m to 6.00m bgl.		

Photograph 5	
Date: 31/10/2024	
Description: BH202 position.	
Photograph 6	
Date: 31/10/2024	
Description: BH202 – Arisings from ground level to 6.00m bgl.	

Photograph 7	
Date: 31/10/2024	
Description: BH201 – backfilled.	
Photograph 8	
Date: 31/10/2024	
Description: BH202 – backfilled.	

