MIDWAY STREET

SJ87943704

SJ87943602

8700BR

8700BR

8700BR

705

G

IC

TL

CB

EIC

WSV

CCTV

WSV

RS

SP

LP

PT

PT

IC

G

LP

DR

Old vented circular cover was found under a steel plate - a depth and photo was taken through the vents (as the cover was rusted and seized in frame! PLEASE NOTE: There is a lot of motor oil contaminates in this area and nothing to stop leakages from seeping into the Surface Water Sewer!! The cover desperately requires a "bund" around it!!

Cover 01 Not on Culvert

Center line of pipe is 0.95m from wall.

SJ87943650
Cover was UTR
C.L.54.55m
I.L.52.45m

Gordon C

N

Legend/Notes:

- Combined Sewer
- Foul Sewer
- SW Sewer
- Assumed Sewer (Not Proven)

INVEK SURVEYS LTD.
Warrington Business Park, Long Lane, Warrington, Cheshire, WA2 8TX
Tel: 01925 244376 Fax: 01925 241517
Email: kevin@invek.com – www.invek.com

Client
Brennan Consult

Drawing Title
816 Stockport Road
Drainage Layout

Scale(s)	N.T.S	Drawn	PW
Date	29.05.24	Checked	RD
Job Number	2257	Approved	KN

Sheet Size, Drawing Number & Revision
A1_2257/01_Rev_00