

Flat 23, 3 Dale Street, Manchester M1 1BA

Existing Window Schedule

Item Reference	Item Location	Existing Window Type	Design / Glazing Bar Layout	Internal Profile	Sash Horns	Condition	Glazing	Internal Colour	External Colour	Reference Images
1	Fourth Floor RHS (rear of the property)	Timber Cord Hung Sash Window	No Glazing Bars	Ovolo	Top and bottom sash horns - type H	- x3 rotten cills - x4 rotten outer jambs - x3 rotten bottom rails - x6 rotten sash stiles	- Single glazed - No historical glass	Grey	Green	Images 1, 2, 8 - 14, 16, 17
2	Fourth Floor RHS (rear of the property)	Timber Cord Hung Sash Window	No Glazing Bars	Ovolo	Top and bottom sash horns - type H	- x1 rotten cill - x1 rotten bottom rail	- Single glazed - No historical glass	Grey	Green	Images 2 - 7, 15-17

Proposed Window Schedule

Item Reference	Item Location	Proposed Window Type	Proposed Design / Glazing Bar Layout	Proposed Internal Profile	Proposed Sash Horns	Proposed Glazing	Proposed Internal Colour	Proposed External Colour
1	Fourth Floor RHS (rear of the property)	Timber Cord Hung Sash Window	No Glazing Bars	Ovolo	Top and bottom sash horns - type H	Double Glazing	Farrow & Ball All White No.2005	Dulux Brunswick Green
2	Fourth Floor RHS (rear of the property)	Timber Cord Hung Sash Window	No Glazing Bars	Ovolo	Top and bottom sash horns - type H	Double Glazing	Farrow & Ball All White No.2005	Dulux Brunswick Green