

pavement delapse

Description
Damage around York
stone

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 11:19

Uploaded By
Carl Barber

File Name
[DDBD0630-9EB7-46BF-...](#)

Location
Butter Lane



pavement delapse

Description
Damage around York
stone flag and also flag
has sunk

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 10:30

Uploaded By
Carl Barber

File Name
[A19758F0-2768-4BE9-9...](#)

Location
Butter Lane



pavement delapse

Description
Damage to edge of stone

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 10:29

Uploaded By
Carl Barber

File Name
[749B7DA4-8D50-49D5-...](#)

Location
Butter Lane



pavement delapse

Description
Sunken and damaged York stone flags and damaged tarmac

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 10:29

Uploaded By
Carl Barber

File Name
[EC450213-3F07-4655-B...](#)

Location
Butter Lane



pavement delapse

Description
Damaged York stone

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 10:29

Uploaded By
Carl Barber

File Name
[C151D228-D1FD-45D5-...](#)

Location
Butter Lane



pavement delapse

Description
Damaged York stone and
tarmac

Taken Date
10/04/2024 at 10:23

Upload Date
10/04/2024 at 10:29

Uploaded By
Carl Barber

File Name
[C72A3748-094A-42C6-B...](#)

Location
Butter Lane



pavement delapse

Description

Cracking to concrete edge
where it meets York stone

Taken Date

10/04/2024 at 10:23

Upload Date

10/04/2024 at 10:28

Uploaded By

Carl Barber

File Name

[26693659-35C8-4344-B...](#)

Location

Butter Lane



pavement delapse

Description

Sunken flag stone and
loose kerb edge

Taken Date

10/04/2024 at 10:23

Upload Date

10/04/2024 at 10:26

Uploaded By

Carl Barber

File Name

[DAB8B47E-25CB-4B4B-...](#)

Location

Butter Lane



pavement delapse

Description

Loose York stones

Taken Date

10/04/2024 at 10:22

Upload Date

10/04/2024 at 10:25

Uploaded By

Carl Barber

File Name

[CE18E658-3823-495F-9...](#)

Location

Butter Lane



pavement delapse

Description

Cracking along edge of
concrete infill

Taken Date

10/04/2024 at 10:22

Upload Date

10/04/2024 at 10:25

Uploaded By

Carl Barber

File Name

[83F68189-6CA8-4F1F-B...](#)

Location

Butter Lane



pavement delapse

Description
York stone damaged


Taken Date
10/04/2024 at 10:22

Upload Date
10/04/2024 at 10:25

Uploaded By
Carl Barber

File Name
[781FEC65-54A0-45EF-B...](#)

Location
Butter Lane



pavement delapse

Description
Damaged tarmac and loose and damaged kerbs

Taken Date
10/04/2024 at 10:22

Upload Date
10/04/2024 at 10:25

Uploaded By
Carl Barber

File Name
[65EC403C-8ECF-4ED2-B...](#)

Location
Butter Lane



pavement delapse

Description
Sunken metal kerb

Taken Date
10/04/2024 at 10:18

Upload Date
10/04/2024 at 10:18

Uploaded By
Carl Barber

File Name
[37D14539-930F-4CA2-A...](#)

Location
Bk Bridge st



pavement delapse

Description
Pothole

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:18

Uploaded By
Carl Barber

File Name
[01DAF9B3-34BC-4466-8...](#)

Location
Bk Bridge st



pavement delapse

Description
Pothole adjacent gully

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:18

Uploaded By
Carl Barber

File Name
[1AE6FD52-A09E-4A5F-B...](#)

Location
Bk Bridge st



pavement delapse

Description
Potholes

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:18

Uploaded By
Carl Barber

File Name
[A97FB986-81C7-4FEC-B...](#)

Location
Bk Bridge st



pavement delapse

Description
Potholes

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:18

Uploaded By
Carl Barber

File Name
[B8E01C26-E6E0-4B57-B...](#)

Location
Bk Bridge st



pavement delapse

Description
Potholes on road and
pavement

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:17

Uploaded By
Carl Barber

File Name
[A21EE5FC-76C8-4707-9...](#)

Location
Bk Bridge st



pavement delapse

Description

Taken Date
10/04/2024 at 10:17

Upload Date
10/04/2024 at 10:17

Uploaded By
Carl Barber

File Name
[4A8B9547-64F8-47FC-8...](#)



pavement delapse

Description

Taken Date
10/04/2024 at 10:16

Upload Date
10/04/2024 at 10:17

Uploaded By
Carl Barber

File Name
[B5B56035-DAEE-4A41-8...](#)



pavement delapse

Description
Blocked twin water gully

Taken Date
10/04/2024 at 10:15

Upload Date
10/04/2024 at 10:16

Uploaded By
Carl Barber

File Name
[5AFFBBD0-43C6-455F-B...](#)

Location
Southgate



pavement delapse

Description
Damaged road tarmac

Taken Date
10/04/2024 at 10:09

Upload Date
10/04/2024 at 11:22

Uploaded By
Carl Barber

File Name
[62D6B7F8-863B-4C78-B...](#)

Location
Southgate



pavement delapse

Description
Damaged tarmac

Taken Date
10/04/2024 at 10:09

Upload Date
10/04/2024 at 10:10

Uploaded By
Carl Barber

File Name
[F0D5A85D-AD48-494E-...](#)

Location
Southgate



pavement delapse

Description
Loose kerb stones and
drain blockage

Taken Date
10/04/2024 at 10:09

Upload Date
10/04/2024 at 10:10

Uploaded By
Carl Barber

File Name
[909A85CE-F6B4-4F85-B...](#)

Location
Southgate



pavement delapse

Description

Taken Date

10/04/2024 at 10:09

Upload Date

10/04/2024 at 10:09

Uploaded By

Carl Barber

File Name

8CD8C6BF-89F6-4297-B...



pavement delapse

Description

Sunken pavement tarmac
and cracking along side 5
no pavement light wells

Taken Date

10/04/2024 at 10:08

Upload Date

10/04/2024 at 10:09

Uploaded By

Carl Barber

File Name

3A9509FC-E96D-40E8-B...

Location

Southgate



pavement delapse

Description

Taken Date

10/04/2024 at 10:08

Upload Date

10/04/2024 at 10:09

Uploaded By

Carl Barber

File Name

[960E69F6-2AE5-4F5F-A...](#)



pavement delapse

Description

Cracked and missing
tarmac outside San Carlo

Taken Date

10/04/2024 at 10:08

Upload Date

10/04/2024 at 10:09

Uploaded By

Carl Barber

File Name

[4388EAA7-7945-46DA-8...](#)

Location

Southgate



pavement delapse

Description

Cracked tarmac out side entrance of San Carlo

Taken Date

10/04/2024 at 10:08

Upload Date

10/04/2024 at 10:08

Uploaded By

Carl Barber

File Name

[9CFBFFE2-1270-48CC-B...](#)

Location

Southgate



pavement delapse

Description

Missing tarmac and broken kerbs

Taken Date

10/04/2024 at 10:00

Upload Date

10/04/2024 at 11:19

Uploaded By

Carl Barber

File Name

[19841366-0123-48DA-B...](#)

Location

King st



pavement delapse

Description
Cracked concrete to
Korean door entrance

Taken Date
10/04/2024 at 10:00

Upload Date
10/04/2024 at 10:01

Uploaded By
Carl Barber

File Name
[89DA5D3B-9092-4EC7-B...](#)

Location
King st



pavement delapse

Description
Loose kerbstones

Taken Date
10/04/2024 at 10:00

Upload Date
10/04/2024 at 10:01

Uploaded By
Carl Barber

File Name
[914874EA-7103-4327-8...](#)

Location
King st



pavement delapse

Description
Damaged and sunken
tarmac

Taken Date
10/04/2024 at 09:59

Upload Date
10/04/2024 at 10:01

Uploaded By
Carl Barber

File Name
[85E66D22-7C01-4EAB-8...](#)

Location
King st



pavement delapse

Description
Loose kerb stones

Taken Date
10/04/2024 at 09:59

Upload Date
10/04/2024 at 10:01

Uploaded By
Carl Barber

File Name
[379EF2E6-8B64-4E95-A...](#)

Location
King st



pavement delapse

Description

Damaged and sunken
concrete around old
pavement light wells

Taken Date

10/04/2024 at 09:59

Upload Date

10/04/2024 at 10:01

Uploaded By

Carl Barber

File Name

[65AD8A9D-F05A-424F-9...](#)

Location

King st



pavement delapse

Description

Taken Date

10/04/2024 at 09:59

Upload Date

10/04/2024 at 10:01

Uploaded By

Carl Barber

File Name

[3BE9DCFB-AF56-4FB8-8...](#)



pavement delapse

Description

Taken Date

10/04/2024 at 09:59

Upload Date


10/04/2024 at 10:01

Uploaded By

Carl Barber

File Name

[3DC15559-DE16-4DE2-...](#)



pavement delapse

Description

Taken Date

10/04/2024 at 09:58

Upload Date

10/04/2024 at 10:00

Uploaded By

Carl Barber

File Name

[AE62CFCF-D768-472B-A...](#)



pavement delapse

Description
Damaged old pavement
lights infills

Taken Date
10/04/2024 at 09:58

Upload Date
10/04/2024 at 10:00

Uploaded By
Carl Barber

File Name
[B25C7AD4-FD2A-4A48-...](#)

Location
King st



pavement delapse

Description
Cracked concrete outside
San Carlo

Taken Date
10/04/2024 at 09:58

Upload Date
10/04/2024 at 10:00

Uploaded By
Carl Barber

File Name
[7CB7EA84-76C9-4165-B...](#)

Location
King st



pavement delapse

Description

Cracked concrete outside
San Carlo

Taken Date

10/04/2024 at 09:58

Upload Date

10/04/2024 at 09:58

Uploaded By

Carl Barber

File Name

[778F33E6-3434-403B-B...](#)

Location

King st

