

Inspection Summary

Project Name:
North Road, Manchester,
M11 4NE 08.1.23

Project number:

Contact:

Date:
08/11/2023

Total Length of sewer network	10.84 m
Inspected Length of sewer network	10.84 m
Not inspected Length of sewer network	0.00 m
Total Length of sewer network (abandoned)	0.00 m
Inspected Length of Sewer network (abandoned)	0.00 m
Not inspected Length of sewer network (abandoned)	0.00 m
Total Length of house connections (satellite)	0.00 m
Inspected Length of house connections (satellite)	0.00 m
Not inspected Length of house connections (satellite)	0.00 m
Number of Sections	1
Number of sections (abandoned)	0
Number of house connections	0
Number of Photos	2

Inspection Summary

Project Name: North Road, Manchester,	Project Number:	Contact:	Date: 08/11/2023	
--	-----------------	----------	---------------------	--

M11 4NE 08.1.23

Place:	Manchester	Section length:	10.84 m
Road:	Barrington Street	Pipe length:	
U/S MH:	MH01	Material:	Vitrified clay
D/S MH:	MH022	Shape:	Circular

	MH022	0.00	MH	Start node type, manhole, reference number : MH022	0
		0.00	WL	Water level, 5% of the vertical dimension	0
	MH01	10.84	MHF	Finish node type, manhole reference number: MH01	0

Project-informationProject name :
North Road, Manchester, M11 4NE 0

Project Number :

Contact :

Date :
08/11/2023

Client: **Gavin Brindle**
Contact Name: **Brindle and Yam Solicitors**
Department:
Road:
Town:
County:
Telephone:
Fax:
Mobile:
E-mail: **gavin@bysolicitors.com**

Site: **North Road, Manchester, M11 4NE**
Contact Name: **Gavin Brindle**
Department:
Road: **North Road**
Town: **Manchester**
County:
Telephone:
Fax:
Mobile:
E-mail:

Contractor **Sewer Drainage Specialist**
Contact Name: **Jake Boydell**
Department: **Drainage**
Road: **Manchester Road**
Town: **Warrington**
County: **Cheshire**
Telephone: **07799803317**
Fax:
Mobile:
E-mail: **Jake.Boydell@sds-solutions.co.uk**

Inspection report

Date : 08/11/2023	Job number :	Weather : no rain or snow	Operator : Aden	Section number : 1	PLR SUFFIX: X
Weather no rain or snow	Vehicle : VEHICLE 1	Camera : camera 1	Preset :	Cleaned : no	Operator : Aden

Place : Road : Location Inspection	Manchester Barrington Street Road MH022 (U/S) MH01	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH01 1.4 MH022
Direction Use:	Combined	Pipe shape :	Circular	
Year laid :		Pipe size :	225 mm	
Purpose :	Investment planning	Pipe material :	Vitrified clay	
Total length :	10.84 m	Lining :		

Comment :

1:90 Position Observation

MH022

0.00

Start node type, manhole, reference number : MH022

0.00

Water level, 5% of the vertical dimension



0 m



10.84 m

10.84

Finish node type, manhole reference number: MH01

MH01

Depth: 1.4

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Place :

Sewer Drainage Specialist

Manchester Road

Warrington

Tel: 07799803317

Fax:

Email: Jake.Boydell@sds-solutions.co.uk

Inspection pictures

Place :
Manchester

Road :
Barrington Street

Date :
08/11/2023

Section number :
1

PLR Suffix :
X



Photo: 1_1_1_A.jpg
0m, Start node type, manhole, reference number : MH022



Photo: 1_1_4_A.jpg
10.84m, Finish node type, manhole reference number: MH01