


139313/FO/2024 Hollinwood Workshop, Clayton Street, Manchester,

Internal Photo Montage



1. Main hall retain all features, upgrade lighting, windows and floor. Redecorate.



2. Photo showing general state of repair.



Removal of unsafe structures



Open up Blocked window apertures and install windows for natural light.



Open up Blocked window apertures and install windows for natural light.



Remove incomplete building projects



Replace all ceilings and Lighting

External Photo Montage



North Elevation



East Elevation



West Elevation