

1. 2.

for

denotes approximate locations
of masonry cracks from ARP
bone survey

denotes approximate locations
of masonry cracks and defects
from CES site survey.
open joints

Revision History [present & previous revision only]

Notes:

to:

Checked:

Notes:

te:

te: 1-9-23

3

1. Bastford

Checked:

Sheet Size: A3

Scale: NTS

Project Number:
CN23-016-J

**CORROSION
ENGINEERING
SOLUTIONS**

Unit S1, 64-66 Akeman Street,
Ting, Hertfordshire, HP23 6AF
T: +44 (0) 1442 767 899
E: info@corrosionengineering.co.uk
W: www.corrosionengineering.co.uk

Project:

Hotel Gotham, Manchester

Drawing Title

Defect Locations on King Street

Client:

Marshall Commercial
Property Development Ltd

Drawing No.:

CN23-016-J722-SK004

rev:

00

