
De-lap report

31/01/2024



Pages 3 and 4

slides 2,5,6 and 7

Slides 8,9,10 and 11

Slides 12 and 13

Slides 14,15,16 and 17

Slides 18, 19 and 20

Slides 23 and 24

Slides 21 and 22

Entrance to Thurloe street off Wilmslow road-







Cracking to the tactical paving flags leading onto the crossing of Thurloe street.

Entrance to Thurloe street off Wilmslow road -





Damage to the traffic bollard in the central reservation on Wilmslow road.

Cracking on the road/cycle path around manhole entering Thurloe street.



Entrance to Thurloe street off Wilmslow road-



Pothole on Wilmslow road.



Faded road markings.



Thurloe street-





Damaged/ dipping curb.



Thurloe street-







Thurloe street-








Cracking tarmac on Thurloe street.

Thurloe street-








Damaged curbs on Thurloe street.

Thurloe street-







Cracking tarmac on Thurloe street outside other construction site.

Thurloe street- Just before the college entrance







Thurloe street/ entrance to college-







Cracking on the pavement around the drain right on entry to the college.

Dipping curb.

More Images of college entrance at the end of Thurloe street-



More views of cracking pavement



Damage to pavement/road next to curb



Wall posts and wall at the entrance to the college-









Path leading away from college entrance-









Cracking on pavement.

Thurloe street- Road outside college entrance






Damaged/un-straight bollard.




More of cracked pavement outside entrance.

Towards the end of Thurloe street-








Where Thurloe street switches to crescent range-



Faded road markings.



Damage/dipping to pavement/curb that leads to gated apartment community.



Start of crescent range-



Major cracking on pavement





Pavement area outside of what would be the pedestrian route for site-





Major cracking/ damage to pavement outside pedestrian entrance on crescent range



Pedestrian entrance wall posts/ crescent range-









Wall going along the pavement of crescent range-





Pavement/ wall going along crescent range-







More images showing the damaged/ cracking pavement on crescent range.

Crescent range/ Thurloe street leading onto park crescent-





Damage to the road leading onto park crescent



Crescent range/ Thurloe street
leading onto Park Crescent-



