

VICTORIA MILL – EQUIPMENT VISUALS


IMAGE	DESCRIPTION
	SUSPENDED OFFICE LIGHTING
	


IMAGE	DESCRIPTION
 A single square recessed office lighting fixture, likely a LED panel light, shown against a plain white background. The fixture has a slightly textured surface and a thin black border.	RECESSED OFFICE LIGHTING
 A photograph of a modern office interior. The ceiling is a white grid with several square recessed lighting fixtures. The office has glass partitions, some of which are tinted green. In the foreground, there are computer monitors and desks. The background shows a large window with a view of a green landscape.	

IMAGE	DESCRIPTION
	RECESSED DOWNLIGHT
	

IMAGE	DESCRIPTION
	BULKHEAD LIGHTING
	


IMAGE	DESCRIPTION
	EMEGRENCY ESCAPE SIGNAGE
	


IMAGE	DESCRIPTION
	CABLE BASKET

IMAGE	DESCRIPTION
	CABLE TRAY

IMAGE	DESCRIPTION
	PANEL HEATER
	


IMAGE	DESCRIPTION
 A photograph of a rectangular, black Heat Recovery Ventilation (HRV) unit against a solid blue background. The unit has two large, circular, silver-colored duct ports on the front face. A white label with technical specifications is visible on the top left of the unit's front panel.	HEAT RECOVERY VENTILATION UNIT
 A photograph showing a complex installation of large, silver-colored metal ductwork in a ceiling space. The ducts are connected to a central rectangular unit, likely the HRV unit shown in the first image. The installation is set within a ceiling with exposed metal trusses and other mechanical components. A fluorescent light fixture is visible in the lower part of the frame.	

IMAGE	DESCRIPTION
	VENTILATION GRILLE
