



Project

Project Name: MOSTON CAMPUS MANCHESTER

Project Date: 11/12/2023

Inspection Standard: MSCC5 Sewers & Drainage GB (SRM5 Scoring)



Table of Contents

Project Name
MOSTON CAMPUS MANCHESTER

Project Number

Project Date
11/12/2023

Project Information	P-1
Section Item 1: WC1 > WC2 (WC1X)	1
Section Item 2: WC2 > WC3 (WC2X)	2
Section Item 3: WC3 > WC4 (WC3X)	3
Section Item 4: WC4 > WC5 (WC4X)	4
Section Item 5: WC5 > WC6 (WC5X)	5
Section Item 6: WC6 > WC7 (WC6X)	6
Section Item 7: WC7 > WC8 (WC7X)	7
Section Item 8: WC8 > WC9 (WC8X)	8



WinCan

Project Information

Project Name
MOSTON CAMPUS MANCHESTER

Project Number

Project Date
11/12/2023




Section Inspection - 11/12/2023 - WC1X

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
1	1	11/12/23	10:01	Not Specified	Not Specified	Not Specified	WC1X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:	Manchester	Inspection Direction:	Downstream	Upstream Node:	WC1
Road:		Inspected Length:	4.80 m	Upstream Pipe Depth:	
Location:		Total Length:	10.00 m	Downstream Node:	WC2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular	Dia/Height:	450 mm
Type of Pipe:		Material:	Concrete	Lining Type:	No Lining
Flow Control:		Lining Material:	No Lining		
Year Constructed:	Not Specified				
Inspection Purpose:					

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC2X

Item No. 2	Insp. No. 1	Date 11/12/23	Time 10:07	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR WC2X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village: Manchester		Inspection Direction: Downstream	Upstream Node: WC2
Road:		Inspected Length: 37.76 m	Upstream Pipe Depth:
Location:		Total Length: 37.76 m	Downstream Node: WC3
Surface Type:		Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular		
Type of Pipe:	Dia/Height: 450 mm		
Flow Control:	Material: Concrete		
Year Constructed: Not Specified	Lining Type: No Lining		
Inspection Purpose:	Lining Material: No Lining		

Comments:

Recommendations:

Scale: 1:327 Position [m] Code Observation MPEG Photo Grade

Depth: m
WC2



0.00

MH

Start node, manhole, reference: WC2



37.76

MHF

Finish node, manhole, reference: WC3

WC3
Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC3X

Item No. 3	Insp. No. 1	Date 11/12/23	Time 10:11	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR WC3X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Manchester	Inspection Direction:	Upstream	Upstream Node:	WC3
Road:		Inspected Length:	17.10 m	Upstream Pipe Depth:	
Location:		Total Length:	17.10 m	Downstream Node:	WC4
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	300 mm		
Flow Control:		Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:		Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:149 Position [m] Code Observation MPEG Photo Grade

Depth: m
WC4



0.00

MH

Start node, manhole, reference: WC4



17.10

MHF

Finish node, manhole, reference: WC3



WC3
Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC4X

Item No. 4	Insp. No. 1	Date 11/12/23	Time 10:13	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR WC4X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village: Manchester	Inspection Direction: Upstream	Upstream Node: WC4
Road:	Inspected Length: 63.67 m	Upstream Pipe Depth:
Location:	Total Length: 63.67 m	Downstream Node: WC5
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 300 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:

Recommendations:

Scale: 1:552 Position [m] Code Observation MPEG Photo Grade

Depth: m
WC5



0.00

MH

Start node, manhole, reference: WC5



63.67

MHF

Finish node, manhole, reference: WC4



WC4
Depth: m

Construction Features

Miscellaneous Features

Structural Defects

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC5X

Item No. 5	Insp. No. 1	Date 11/12/23	Time 10:18	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR WC5X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Manchester	Inspection Direction:	Downstream	Upstream Node:	WC5
Road:		Inspected Length:	9.47 m	Upstream Pipe Depth:	
Location:		Total Length:	9.47 m	Downstream Node:	WC6
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	300 mm		
Flow Control:		Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:		Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:82 Position [m] Code Observation MPEG Photo Grade

Depth: m
WC5



0.00

MH

Start node, manhole, reference: WC5



9.47

MHF

Finish node, manhole, reference: WC6



WC6
Depth: m

Construction Features

Miscellaneous Features

Structural Defects

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC6X

Item No. 6	Insp. No. 1	Date 11/12/23	Time 10:20	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR WC6X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Manchester	Inspection Direction:	Upstream	Upstream Node:	WC6
Road:		Inspected Length:	23.47 m	Upstream Pipe Depth:	
Location:		Total Length:	23.47 m	Downstream Node:	WC7
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	300 mm		
Flow Control:		Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:		Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:204	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m WC7 0.00							

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 11/12/2023 - WC7X

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
7	1	11/12/23	10:22	Not Specified	Not Specified	Not Specified	WC7X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:	Manchester	Inspection Direction:	Downstream	Upstream Node:	WC7
Road:		Inspected Length:	11.00 m	Upstream Pipe Depth:	
Location:		Total Length:	11.00 m	Downstream Node:	WC8
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	300 mm		
Flow Control:		Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:		Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:96 Position [m] Code Observation MPEG Photo Grade

Depth: m
WC7



0.00

MH

Start node, manhole, reference: WC7



11.00

MHF

Finish node, manhole, reference: WC8



WC8
Depth: m

Construction Features

Structural Defects

Miscellaneous Features


Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
8	1	11/12/23	10:24	Not Specified	Not Specified	Not Specified	WC8X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:	Manchester	Inspection Direction:	Downstream	Upstream Node:	WC8
Road:		Inspected Length:	12.80 m	Upstream Pipe Depth:	
Location:		Total Length:	12.80 m	Downstream Node:	WC9
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	300 mm		
Flow Control:		Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:		Lining Material:	No Lining		
Comments:					
Recommendations:					



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0