

APPENDIX IV PHOTOGRAPHS

PLATE 1 SITE ENTRANCE VIA KENYON LANE



PLATE 2 VIEW OF SOUTH OF SITE FACING EAST



PLATE 3 VIEW OF NORTH OF SITE FACING KENYON LANE AND BACKILLED TRIAL PIT



PLATE 4 SOUTH WEST CORNER OF THE SITE AND BACKFILLED TP101



PLATE 5 FOOTPATH RUNNING ALONG WESTERN AND NORTHERN BOUNDARY



PLATE 6 TP101 EXCAVATION AND ARISING



PLATE 7 TP103 EXCAVATION AND ARISING



PLATE 8 TP107 EXCAVATION AND ARISING



PLATE 9 TP109 EXCAVATION AND ARISINGS



PLATE 10 WS102 ARISINGS AND MONITORING WELL



PLATE 11 WS104 ARISINGS AND MONITORING WELL



APPENDIX V

E3P EXPLORATORY HOLE LOGS

Project Name: Kenyon Lane	Project No. 16717	Co-ords: 387579.00 - 401148.00 Level:	Date 22/06/2023
Location: Failsworth	Dimensions (m): 2.00 Depth 3.60		Scale 1:30
Client: AJP			Logged E. Canham

Water Strike	Samples & In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description	
	Depth	Type	Results					
				0.30			MADE GROUND: Brown slightly gravelly clayey medium to coarse sand with frequent roots and rootlets. Gravel is fine to coarse subangular to angular of brick and mudstone. (Topsoil)	
							MADE GROUND: Brown sandy reworked clay.	
	1.20	ES		0.90			MADE GROUND: Light grey slightly gravelly clayey fine to medium sand with pockets of orangish pink silty clay. Gravel is fine to medium subangular to angular of brick and clinker.	1
	2.00	B						2
				3.40				3
				3.60			MADE GROUND: Orangish greyish brown slightly gravelly silty clay. Gravel is fine to medium subangular to angular of ash, wood, and organic matter. End of Pit at 3.60m	4

Trial Pit Photographs



Trial Pit 101



Trial Pit 101 Spoil

Remarks: 1. Complete. 2. Depth of Made Ground unproven.

Stability: Stable.

Project Name: Kenyon Lane	Project No. 16717	Co-ords: 387630.00 - 401161.00 Level:	Date 22/06/2023
Location: Failsworth	Dimensions (m): 2.20 Depth 1.20		Scale 1:30
Client: AJP			Logged E. Canham

Water Strike	Samples & In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description	
	Depth	Type	Results					
	0.20	ES		0.30			MADE GROUND: Greyish black slightly gravelly clayey medium to coarse sand with frequent roots and rootlets. Gravel is fine to coarse subangular to angular of brick and mudstone. (Topsoil)	
	0.80	ES		1.10 1.20			MADE GROUND: Greyish brown clayey gravelly medium to coarse sand with pockets of black silty clay and frequent cobbles. Gravel is fine to coarse subangular to subrounded of brick, mudstone and plastic. Cobbles are subangular to angular of intact bricks.	1
							MADE GROUND: Concrete. (Recovered as a greyish brown sandy gravel)	2
							End of Pit at 1.20m	3
								4

Trial Pit Photographs



Trial Pit 102

Trial Pit 102 Spoil

Remarks: 1. Terminated on concrete slab at 1.20 m bgl. 2. Strong hydrocarbon odour encountered from 0.70 m bgl.

Stability: Stable.

Project Name: Kenyon Lane	Project No. 16717	Co-ords: 387648.00 - 401171.00 Level:	Date 22/06/2023
Location: Failsworth	Dimensions (m): 2.20 Depth 2.50		Scale 1:30
Client: AJP			Logged E. Canham

Water Strike	Samples & In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description	
	Depth	Type	Results					
				0.25			MADE GROUND: Brown slightly gravelly clayey medium to coarse sand with frequent roots and rootlets. Gravel is fine to coarse subangular to angular of brick and mudstone. (Topsoil)	
	2.00	ES		2.50			MADE GROUND: Greyish brown clayey gravelly medium to coarse sand with frequent cobbles. Gravel is fine to coarse subangular to subrounded of mudstone, glass and brick. Cobbles are subangular to angular of bricks, metal, plastic and wood.	
							End of Pit at 2.50m	

Trial Pit Photographs



Trial Pit 103

Trial Pit 103 Spoil

Remarks: 1. Terminated at 2.50 m bgl due to large concrete blocks restricting excavation. 2. Slight organic odour encountered within Made Ground.

Stability: Stable.