

DOMIS

Hazard Identification
(if none state 'None
relevant')

None Assessed/Not Used

- a) not likely to be obvious to a competent contractor or other designers;
- b) unusual; or
- c) likely to be difficult to manage effectively

Do not scale from this drawing. All dimensions to be verified on site prior to the commencement of any work or the production of any shop drawings. All discrepancies to be reported to Bryden Wood Ltd. This drawing is to be read in conjunction with all related Consultant's drawings and any other relevant information. This drawing is the copyright of Bryden Wood Ltd.

Victoria House

Facade - Typical Bat and Bird box


22017-BWT-ZZ-XX-DR-Y-0073

As indicated A3 S3 P01



Bryden Wood
101 Euston Road
London, NW1 2RA, UK

- No cavities to be allowed during insulation installation



4

Typical Detail_A_Vertical
1:5