

Form detail

#163: Drainage Pipework Inspection Checklist




Form details

Location	
Form date	Jun 13, 2022
Description	External drainage
Submitted by	John Carroll
Status	Submitted
Last update	Jun 16, 2022, 11:08 AM BST
Last updated by	John Carroll
Included references	Assets Documents Form details Issues Photos

1. Drainage Pipework Inspection Checklist

- 1.1 Project Name
MAL
- 1.2 Date
Jun 13, 2022
- 1.3 Location / Area / GL Ref
External area
Drainage
- 1.4 Specification / Drawing Reference
Drainage layout plan
- 1.5 Downstream /Upstream MH Reference
Upstream FW IC02
Downstream FW IC06

- 1.6 Pipe Diameter as per design. Note pipe size
150mm clay
- 1.7 Pipework Type: Foul / Storm Water / Combined
Foul
- 1.8 Pipework Product: Concrete / Plastic / Ductile / Clay
Clay

Photos (1)[20220614_151357_photo](#)**Added on** Jun 14, 2022, 3:14 PM BST**Added by** John Carroll

- 1.9 Connection onto existing Sewer / Culvert completed and made good
☐ Yes ☐ No ☒ N/A
- 1.10 Pipework Bed and Surround installed as specified
☒ Yes ☐ No ☐ N/A

Photos (6)



[20220613_153133_photo](#)

Added on Jun 13, 2022, 3:55 PM BST

Added by John Carroll



[20220613_140051_photo](#)

Added on Jun 13, 2022, 3:55 PM BST

Added by John Carroll



[20220610_110101_photo](#)

Added on Jun 10, 2022, 11:10 AM BST

Added by John Carroll



[20220610_085711_photo](#)

Added on Jun 10, 2022, 9:07 AM BST

Added by John Carroll

[20220610_075002_photo](#)

Added on Jun 10, 2022, 9:07 AM BST

Added by John Carroll

[20220610_074601_photo](#)

Added on Jun 10, 2022, 9:07 AM BST

Added by John Carroll

1.11 Pipe trench back filled with specified backfill material



Yes



No



N/A

Photos (3)

[20220613_153309_photo](#)

Added on Jun 13, 2022, 3:56 PM BST

Added by John Carroll

[20220613_153214_photo](#)

Added on Jun 13, 2022, 3:56 PM BST

Added by John Carroll



[20220613_140051_photo](#)

Added on Jun 13, 2022, 3:55 PM BST

Added by John Carroll

- 1.12 HOLD POINT: Air test completed to pipework and witnessed by client (Insert Name)
Kate Miller

HOLD POINT: Air test Client Signature

Name

Kate miller

Date

June 16, 2022

- 1.13 HOLD POINT: Air test completed to pipework and witnessed by client (Insert Photo)



Yes



No



N/A

Photos (1)



[20220613_140100_photo](#)

Added on Jun 13, 2022, 3:55 PM BST

Added by John Carroll

1.14 HOLD POINT: Final Inspection by Client (Insert Name)
Kate Miller

HOLD POINT: Final Inspection by Client (Insert Signature)

K Miller

Name

Kate miller

Date

June 16, 2022