




KEY

- Inspection Chamber
- ➔ Directional Flow
- Soil Vent Pipe
- Gully
- Rainwater Pipe
- X Fault

NOTES NOT TO SCALE

DISTANCE, DIRECTION AND LOCATIONS OF DRAINAGE RUNS SHOWN ON THIS PLAN ARE ALL APPROXIMATE AND SHOULD NOT BE USED AS AN ACCURATE REFERENCE.

UTL = Unable To Lift

Title: Blackfriars Street, Manchester

Drawn by: MJ

Date: 24.05.21

Approved By:

Date:

Drawing Number: Aqua -