

Form detail

#150: Manhole / Chamber Inspection Checklist



Forms

Location

Form date Jun 8, 2022

Description FW01 combined

Due date

Submitted by John Carroll

Status Closed

Last update Jun 30, 2022, 11:49 AM BST


Last updated by John Carroll

Included references Assets | Files | Forms | Issues | Photos

1. Manhole / Chamber Inspection Checklist

- 1.1 Project Name
Mal
- 1.2 Date
Jun 7, 2022
- 1.3 Location / Area / GL Ref
External slab
- 1.4 Specification / Drawing References
DR01
Drainage layout plan

Photos (1)



20220525_131601_photo

Taken on May 25, 2022, 1:16 PM BST**Added on** May 25, 2022, 1:28 PM BST**Added by** John Carroll

1.5 MH / Chamber Reference

FW01

1.6 Chamber Type: Foul Water / Storm Water / Combined

Combined

1.7 Chamber Entry Type: Step Irons / Ladder / PPIC

Steps

1.8 Channels installed as required



Yes



No



N/A

Photos (1)



20220531_161128_photo

Taken on May 31, 2022, 4:11 PM BST**Added on** Jun 1, 2022, 11:05 AM BST**Added by** John Carroll

1.9 Concrete surround installed around chamber as required / Widewall rings seals used

☐

Yes

☐

No

☒

N/A

1.10 Benching / floor complete and of an acceptable standard

☐

Yes

☒

No

☐

N/A

1.11 All pipe entries sealed as required

☐

Yes

☒

No

☐

N/A

1.12 Safety chains correctly installed if required

☐

Yes

☐

No

☒

N/A

1.13 Raising Pieces / Correct courses of brickwork installed, clean & pointed to acceptable standard

☐

Yes

☐

No

☒

N/A

1.14 All ring joints been pointed correctly

☒

Yes

☐

No

☐

N/A

1.15 Chamber free from leaks



Yes



No



N/A

1.16 Chamber clean & free of debris



Yes



No



N/A

Photos (1)

20220620_091722_photo

Taken on Jun 20, 2022, 9:17 AM BST**Added on** Jun 21, 2022, 11:11 AM BST**Added by** John Carroll

1.17 Correct cover class and depth installed correctly



Yes



No



N/A

Photos (6)



20220606_143320_photo

Taken on Jun 6, 2022, 2:33 PM BST**Added on** Jun 7, 2022, 3:15 PM BST**Added by** John Carroll

20220606_143151_photo

Taken on Jun 6, 2022, 2:31 PM BST**Added on** Jun 7, 2022, 3:15 PM BST**Added by** John Carroll

20220606_142745_photo


Taken on Jun 6, 2022, 2:27 PM BST**Added on** Jun 7, 2022, 3:15 PM BST**Added by** John Carroll

20220606_142726_photo

Taken on Jun 6, 2022, 2:27 PM BST**Added on** Jun 7, 2022, 3:15 PM BST**Added by** John Carroll



20220606_110736_photo

Taken on Jun 6, 2022, 11:07 AM BST**Added on** Jun 7, 2022, 8:31 AM BST**Added by** John Carroll

20220531_161128_photo

Taken on May 31, 2022, 4:11 PM BST**Added on** Jun 1, 2022, 11:05 AM BST**Added by** John Carroll

1.18 HOLD POINT: Final Inspection completed by Client and Signed off



Yes



No



N/A

Photos (1)



20220629_083237_photo

Taken on Jun 29, 2022, 8:32 AM BST**Added on** Jun 30, 2022, 8:04 AM BST**Added by** John Carroll

1.19 HOLD POINT: Final Inspection completed by Client and Signed off (Insert Name)
Kate Miller

HOLD POINT: Final Inspection completed by Client and Signed off (Insert Signature)



Name	Date and time
-	Jun 30, 2022 at 11:48 AM BST