




GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview photograph of the area verified during this visit.




GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview photograph of the area verified during installation






GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview photograph of the area verified during installation





GEOSHIELD Verification Report



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Upper Raft Slab - Pour 2

NOTES: Taped Lap Joint

Visqueen Standard Gas Barrier has been installed to the area of the Upper Raft Slab

Pour 1 Overlaps of 100mm minimum have been created which have been sealed using

Visqueen double sided butyl tape. Silver foil tape has then been used to complete the



lap joint creating a continuous barrier. The left photo shows the Visqueen Double Sided

Butyl Tape used during the install, whilst the right photo shows the application of both

GEOSHIELD Verification Report

VERIFICATION ITEM ONE



the double sided tape and foil tape. Air lancing was not undertaken due to lack of access, however a thorough pick and probe test was carried out to ensure no faults were caused.