

GEOSHIELD Verification Report

BGA
British Geomembrane Association




VERIFICATION ITEM ONE

LOCATION/GRID LINE: Upper Raft Slab

NOTES: Taped Lap Joints

Visqueen Standard Gas Barrier has been installed across the verified area and overlaps of 100mm have been created, they have then been sealed using 40mm double sided butyl tape forming a continuous barrier. The photos below show the installation of



membrane and the double sided butyl tape.

GEOSHIELD Verification Report

VERIFICATION ITEM ONE



This shows a close up of the double sided butyl tape. The joints were complete with silver foil tape and no defects found during the verification process.