


ROOM F.24

- No cornice
- Ceiling has collapsed completely leaving exposed the timber rafters above



ROOMS F.26 / F.27 / F.28 / F.29

- Restricted access - Rooms are inaccessible due to collapsed ceiling and/or unsafe floor structure
- Limited cornice as noted on the plan
- Most of the ceiling has collapsed - the rest looks badly damaged



ROOM F.25

- Restricted access - Room is inaccessible due to collapsed ceiling and/or unsafe floor structure
- No cornice
- All ceiling has collapsed exposing a precast concrete floor above

