



PHOTO 01 – External, junction of Cross Street to King Street



PHOTO 02 – External, junction of Cross Street to Town Hall Lane



PHOTO 03 – External, King Street façade




PHOTO 04 – External, 37 Cross Street roof plan



PHOTO 05 – Internal, underside of timber staircase



PHOTO 06 – Internal, underside of timber landing (staircase)



PHOTO 07 – Internal, poorly installed fire door




PHOTO 08 – Internal, poorly installed fire rated glazing unit



PHOTO 09 – Internal, riser cupboard on communal landings



PHOTO 10 – Internal, concealed poorly fire stopped penetration



PHOTO 11 – Internal, concealed poorly fire stopped penetration



PHOTO 12 – Internal, concealed poorly fire stopped penetration