






Photograph:	1	-	Exit sign – Surface mounted exit sign – no longer complies with BS 5499
-------------	---	---	---



Photograph:	2	-	Ceiling mounted exit sign – does not comply with BS 5499
-------------	---	---	--




Photograph:	3	-	Final exit door with no external emergency lighting
-------------	---	---	---



Photograph:	4	-	Final exit door with no exit sign
-------------	---	---	-----------------------------------



Photograph:	5	-	Example of existing external emergency bulkhead
-------------	---	---	---



Photograph:	6	-	Example of external emergency bulkhead.
-------------	---	---	---



Photograph:	7	-	Proposed replacement final exit sign – Dextra EXI LED
-------------	---	---	---



Photograph:	8	-	Proposed emergency bulkhead – Dextra AME2 LED
-------------	---	---	---



Photograph:	9	-	Proposed emergency bulkhead front entrance – Dextra Tanek
-------------	---	---	---