

ARTEZ

Crusader Works, Manchester
Underground Drainage records
Rev A





Building 2: internal drainage



Building 2: Drainage passing from the building into the courtyard



Courtyard: manhole construction



Building 3: Foul drainage



Building 2: Drainage passing below spine wall



Building 1: Foul drainage



Building 2: formation after drainage





Floor reinstatement, after drainage



Building 3: Drainage




Building 2: drainage connection to manhole



Courtyard: Manhole construction



Surface water retention tank



Surface water retention tank



Completed drainage to East elevation of the building



Main drain connection



Hydro Break