



SHIP CANAL HOUSE

MANCHESTER

EXISTING SITE PHOTOS

PREPARED BY BLUESKY DESIGN

FOR SAVILLS

DECEMBER 2022

GROUND FLOOR RECEPTION

01	 A photograph of a modern reception area. A dark, L-shaped reception desk is in the center. A person wearing a headscarf is seated behind the desk, and another person is standing to the right. The background features a large, textured wall with a green and brown pattern. The floor is made of light-colored tiles, and the ceiling has recessed linear lighting.	View towards existing reception desk
02	 A photograph of a lift lobby. Three glass-enclosed lifts are visible, set into a white wall. A framed abstract painting hangs on the wall to the right. The floor is tiled, and the ceiling has recessed linear lighting.	View towards lifts
03	 A photograph of a seating area. There are dark blue armchairs and a sofa arranged around a low glass coffee table. Large windows with dark frames provide a view of the outdoors. The ceiling has exposed wooden beams and pendant lights.	View to existing seating area

GROUND FLOOR RECEPTION

04			View of existing rear stairs to accessible entrance
05			Existing lobby domed ceiling
06			View to existing glazed lobby screen

GROUND FLOOR RECEPTION

07	 A photograph showing a view through a large arched doorway into a reception area. In the center, there is a dark reception desk with a person standing behind it. The floor is made of light-colored stone tiles, and the walls are white with grey stone pillars on either side of the archway.	View towards existing reception desk
08	 A photograph of a curved staircase with dark carpeting and ornate metal railings. The stairs are set against a white wall, and the floor at the base is made of light-colored stone tiles.	View to existing stairs
09	 A photograph of an accessible platform lift with a glass railing and a wooden handrail. The lift is located on a light-colored stone tiled floor next to a window.	Existing accessible platform lift

EXISTING STAIRWELL/ LIFT LOBBIES

10	 A photograph of a lift lobby with a curved wall, tiled floor, and two lift doors. A skylight is visible on the ceiling, and a framed picture hangs on the wall.	View of existing lift lobby
11	 A photograph of a stairwell with a curved wall, tiled floor, and a decorative metal balustrade. A skylight is visible on the ceiling.	View to existing stairwell showing skylight and balustrade
12	 A close-up photograph of a wall featuring a decorative mosaic pattern with yellow and blue tiles, set against a background of larger, textured stone tiles.	Feature tiling to stairwell

EXISTING STAIRWELL/ LIFT LOBBIES

13		Skylight to stairwell
14		Existing lift lobby doors to upper floors
15		View to existing stairs

EXISTING STAIRWELL/ LIFT LOBBIES

16			Detail of existing stair balustrade
17			Detail of feature window to stairs
18			View down stairwell