© Survey & Engineering Projects Ltd. 2019
Reproduction in whole or in part by any means is prohibited without the prior permission of Survey & Engineering Projects Ltd.
T. (0161) 7279531 F. (0161) 7272266 W. www.sepsurvey.com E. info@sepsurvey.com

N

PLAN GRID NORTH

File Name: S17569-U.dwg

LEGEND

AV	AIR VALVE	BT	BT
BI	BT INSPECTION COVER	CD	CABLE DUCT
CB	CONTROL BOX	CTV	CABLE TV
COL	COLUMN / LAMP POST	E	ELECTRIC
COM	COMMUNICATIONS COVER	ECP	ELECTRONIC STEP
CTV	CABLE TV COVER	ELE	ELECTRIC
DC	DRAIN CHANNEL	ELEC	ELECTRIC
DP	DOWN PIPE	FO	FIBRE OPTIC
EB	ELEC. BOX	FUEL	FUEL LINE
EIC	ELEC. INSPECTION COVER	GAS	GAS MAIN
EM	ELEC. METER	GAS	GAS SERVICE LINE
EP	EARTH POST	HP	HIGH PRESSURE
FP	ELECTRICITY POLE	MW	MAINS WATER
FL	FLOOR LEVEL (DOOR LEVEL)	SW	SEWER FM
FH	FIRE HYDRANT	SW	SEWER RM
G	GULLY	SW	SEWER UK
GLT	GROUND LIGHTING LIGHT	TEL	TRAFFIC SIGNAL CABLE
GV	GAS VALVE	TEL	TELEPHONE CABLE
ICV	GAS VALVE	UC	UNIDENTIFIED CABLE
IC	INSPECTION COVER	UP	UNIDENTIFIED PIPE
IL	INVERT LEVEL	UTL	UNIDENTIFIED UTILITY CABLE
KO	KERB OUTLET		SURVEY BOUNDARY
LP	LAMP POST		
MH	MANHOLE		
OH	OVERHEAD		
OP	OUTFALL PIPE		
PC	PETROL CAP		
PP	PETROL PUMP		
RE	RODDING EYE		
SDP	SOIL DISCHARGE PIPE		
SOF	SOFFIT LEVEL		
SV	STOP VALVE		
TCB	TELEPHONE CALL BOX		
TL	TRAFFIC LIGHT		
TLB	TRAFFIC LIGHT BOX		
TP	TELEPHONE POLE		
WV	WATER VALVE		
WM	WATER METER		
WST	WATER STOP TAP		
WSV	WATER STOP VALVE		
EOT	END OF TRACE		
NAD	NO ACCESS TO KEY AREA		
UTL	UNABLE TO LIFT		
UTS	UNABLE TO SONDE		
UTT	UNABLE TO TRACE		
SLT	SIGNAL LOSS		
BLK	BLOCKED		
BOL	BOLLARD OTHER SPR CONTACTS		
BSL	BACKDROP MHC		
TMP	TOP OF PIPE		
TOP	TOP OF PIPE		
SYM	SYMBOL		

BT-A	BC-A
BT-B	BC-B
CA-A	CA-A
CA-B	CA-B
CA-C	CA-C
EL-A	EL-A
EL-B	EL-B
EL-C	EL-C
FL-A	FL-A
FL-B	FL-B
GAS-A	GAS-A
GAS-B	GAS-B
MW-A	MW-A
MW-B	MW-B
SW-A	SW-A
SW-B	SW-B
SW-C	SW-C
TEL-A	TEL-A
TEL-B	TEL-B
TEL-C	TEL-C
UC-A	UC-A
UP-A	UP-A

QUALITY LEVEL

A – Verification

B1 – Horizontal/Vertical location using multiple techniques

B2 – Horizontal/Vertical location using a single technique

B3 – Horizontal location using a single technique

B4 – Assumed route

C – Site Reconnaissance

D – Desktop utility records search

NOTES:

All levels relate to O.S (Newlyn) Datum, Established using network RTK. Survey Coordinates on a local grid, orientated to National Grid.
BS5930 Underground Utilities survey was conducted in compliance with the BSI PAS128:2014 standard.
Services linetypes display text indicating thir an abbreviation of the services' function (eg. EL = Electric Cables) followed by the Quality Level to which that service was surveyed (eg. EL-A = Electric Cables Quality Level A).
Quality Level descriptions shown in the above legend are for reference purposes only and are not intended as detailed descriptions.
For full information on Quality Levels, please consult the BSI PAS128:2014 standards document.
Survey Quality Level A is the verification of consistent subsurface anomalies located using the Ground Penetrating Radar and should be considered as Quality Level B2. The nature of these anomalies could not be determine by non-invasive means. GPR lines that were identifiable as a service are shown as their respective service.

DISCLAIMER:

At SEP we use skilled and experienced staff, modern up to date techniques and top of the range electromagnetic and radar technology to locate and trace sub-surface utilities. However the performance of the equipment and the ability of the operator can be adversely affected by factors outside the control of SEP. Therefore we cannot guarantee that all utilities present on site have been located. It is the responsibility of the Client to consult regional authority records and undertake trial digs where appropriate.

Where similar services run in close proximity it may be impossible to separately trace individual services as the trace signal can experience interference. In such cases, services will be shown as a single, unmarked line. The displayed depth will refer to the shallowest detected utility.

Successful tracing of non-conductive materials may be limited. Drainage gullies are also tested where possible to prove connectivity but it is not always possible to introduce the sonde due to narrow pipe sizes and or accumulated silt.

Depth information of underground services/features are generally accurate to within +/- 10%. (i.e. a pipe at 2m deep may be accurate to +/-200mm) but this cannot be guaranteed. Depths shown usually refer to the top of the service, (Unless otherwise stated) and are usually to invert (base of drainage channel) unless otherwise stated.

Some above ground features may have been obscured at time of survey. It is not always possible to operate the Ground Penetrating Radar in areas including, but not limited to, dense vegetation, rubble, debris and/or rough/uneven ground.

Existing record information that was made available to SEP by the Client or by the statutory utility provider should be regarded only as an indication and cannot be guaranteed.

Excavation in the vicinity of services shown should be carried out with due diligence (Ref. HSG47).

062407
Gorton Community Hub
Library Site
Locations for SIte Investigation - internal issue
06.10.2022

PT

0 2m 4m 8m 12m 16m
SCALE BAR

REV.	DATE	DESCRIPTION

SURVEY & ENGINEERING PROJECTS

Client
Morgan Sindall plc
6th Floor, 2 Anchorage Quay
Salford Quays
Manchester
M50 3YW

Project Title
Utility Survey of Land at:
Library Site at Gorton Community Hub
Garratt Way
Manchester
M18 8LD

Surveyed	Drawn	Checked
L.Morris	D.Shipton	L.Morris

Scale	Date	Drawing Ref.	No.	Size	Rev
1:200	Apr 19	S17569-U	01	A0	--