


ROOM F.04

- Cornice as noted on the plan
- What looks like suspended ceiling has gone revealing cornice and plasterboard ceiling




ROOM F.05

- No cornice
- Ceiling in relatively good condition



ROOM F.06

- No cornice
- Partially collapsed ceiling as noted on the plan
 - Ceiling in bad condition
- Exposed pipework where ceiling has collapsed



ROOM F.07

- No cornice
- Partially collapsed ceiling as noted on the plan
 - Ceiling in bad condition
- Exposed pipework where ceiling has collapsed

