



Note:
Do not scale from this drawing.
Dimensions are to be checked on site.
If in doubt please ask.

KEY	
1	Fractures - notes relate to fractures impacting the stability of the stone
2	Loose Stone
3	Stone fully fractured and hole visible
4	Rated Stone
5	Surface Erosion
6	Open Joints
7	Cement Mortar
	Trip Hazard

Rev Date/mts Details

© The moral rights of the author are hereby asserted.
This drawing is the property of Buttress and must not be reproduced without permission.
Buttress Ltd is registered in England and Wales 2580273

Buttress

A1 Bengal St
Manchester
M4 6AF
T 0161 236 3303
E contact@buttress.net
W www.buttress.net

Project Title CSM - College House
Client Chetham's School of Music
Location Manchester

Drawing Title Baronial Hall & Access Corridors
College House Ground Floor 2 of 2
As existing and assessment of condition

Date 26/02/23 **Scale** 1:100
Checked EK **Orig Paper Size** A3

Status **PLANNING**

Project: Origin: Zone: Level: Type: Disc: Number: Rev:

9424-BA - ZZ - 0F - DR - A - (01)003 - -