


ROOM G.05

- Restricted access - Room is inaccessible due to collapsed ceiling and/or unsafe floor structure
- No cornice
- Most of the ceiling has collapsed - the rest looks damaged



ROOM G.06

- Restricted access - Room is inaccessible due to collapsed ceiling and/or unsafe floor structure
- No cornice
- Ceiling is gone completely
- Exposed timber above ceiling looks severely damaged



ROOM G.07

- Restricted access - Room is inaccessible due to collapsed ceiling and/or unsafe floor structure
- No cornice
- Ceiling is gone completely
- Exposed roof timber structure



ROOM G.08

- Cornice as noted on the plan
- Partially collapsed ceiling as noted on the plan
- Plasterboard ceiling
- Ceiling is badly damaged

