

Back Turner Street Masonry Repairs

Item No	Item Description	Photo	Location No Drawing
1	Graffiti Removal		1
2	Stone Repair to windowsill		2
3	Stone Repair to windowsill		3
4	Stone Repair to windowsill		4

5	Stone Repair to windowsill		5
6	Stone Repair to window head		6
7	Stone Repair to window head		7
8	Stone Repair to window head		8
9	Brick Repairs x 10No from Façade Retention		9
10	Brick Repairs x 2		10

11	Brick Repairs x 7		11
12	Brick Repair x 1		12
13	Brick Repairs x 11 No from Façade Retention		13
14	Brick Repairs x 22 No from Façade Retention		14
15	Brick Repairs x 22 No from Façade Retention		15

16	Brick Repairs x 1		16
17	Brick Repairs x 2		17
18	Brick Repairs x 9 No from Façade Retention		18
19	Brick Repairs x 3		19
20	Brick Repairs x 8		20

21	Brick Repairs x 12		21
22	Brick Repairs x 11 No from Façade Retention		22
23	Brick Repairs x 9 No from Façade Retention		23
24	Brick Repairs x 8 No from Façade Retention		24

25	Brick Repairs x 7		25
26	Brick Repairs x 6		26