

Monitoring Details

Provider Name:	My Home Needs Ltd	Monitoring Interval:	2 Monthly
Instruction Date:	28/06/2021	Number of Visits:	5
Reading Date:	27/01/2022	Visits Completed:	5
Date of Issue:	31/01/2022	Visits Outstanding:	0


Client Details

Client:	Crawfords	
Job Reference:	SU2001722	Engineer / Handler: A Mason

Monitored Address

Occupier:	Kingform Ltd
Address:	28 College Road, Whalley Range, Manchester, M16 8FH

Site Plan



Level Readings (Displayed in metres)


Visits	1	2	3	4	📌 DATUM
17/07/2021	10.8275	10.4850	10.4688	10.4851	10.0000
30/07/2021	10.8271	10.4840	10.4689	10.4855	10.0000
06/10/2021	10.8252	10.4820	10.4670	10.4836	10.0000
06/12/2021	10.8270	10.4838	10.4690	10.4852	10.0000
27/01/2022	10.8260	10.4824	10.4679	10.4840	10.0000

DATUM: Datum is a manhole in the road opposite No 36, it has an assumed value of 10.0000m. No suitable secondary TBM available. If this is not suitable please advise if a deep datum is required?

Level Readings Difference (Displayed in millimetres)


Visits	1	2	3	4	📌 DATUM
17/07/2021	N/A	N/A	N/A	N/A	N/A
30/07/2021	-0.40 ↓	-1.00 ↓	0.10 ↑	0.40 ↑	0.00 =
06/10/2021	-1.90 ↓	-2.00 ↓	-1.90 ↓	-1.90 ↓	0.00 =
06/12/2021	1.80 ↑	1.80 ↑	2.00 ↑	1.60 ↑	0.00 =
27/01/2022	-1.00 ↓	-1.40 ↓	-1.10 ↓	-1.20 ↓	0.00 =

Relative Movement (Relative Survey, for illustration purposes only)



Baseline
 Visit 1 (17/07/2021)
 Visit 2 (30/07/2021)
 Visit 3 (06/10/2021)
 Visit 4 (06/12/2021)
 Visit 5 (27/01/2022)

Level Readings Chart



Homeowner Notes

Visit	Homeowner Notes
17/07/2021	No new concerns
06/10/2021	No concerns raised.
06/12/2021	No concerns raised.
27/01/2022	No concerns raised.