

WILES & MAGUIRE

Ref. STAT: 01

The Old Station Master's House, Manchester Reference Photos, August 2022



The Old Stationmasters House alongside the 1830 Station building



The Old Stationmasters House still sits amongst the everyday transit of trains and their rolling stock




The South elevation




The West elevation


WILES & MAGUIRE




The current interior of the main living room and kitchen, still fitted out as an office but unused since March 2020.



The main entrance hallway



The top landing of the staircase with the angled ceiling and rooflight




The staircase mid landing.

WILES & MAGUIRE



Photos of the rear elevation showing the current wall and gates to the yard.



View of the rear yard where the new door is proposed.

Photo of the attic over the main rooms facing Liverpool St showing extensive internal rebuilding using concrete blockwork.



Upper wall is salt damaged and the mortar is washed out as the gutter overflows. Surplus water is penetrating the brickwork of the blank window infill.

WILES & MAGUIRE



Photos showing the set back in the north roof pitch that we propose to infill so that the drainage of those roofs is not concentrated on the back gutter of the chimney stack



Early painting of the building and the bridge over the river (National Trust Collection)



Etching showing the boundary wall of the rear yard



Early C20 photo of the building



Photo of the platform at the time of closure in the 1970s

WILES & MAGUIRE



Photo of the House from the 1970s showing conversion to a shop with the station building to the right.
Taken around the time of final closure