



A handwritten signature in black ink, appearing to read 'Ben Ingham'.

Ben Ingham
J&B Installation Group Ltd

UNAGI CHEETHAM HILL

canopy , extract and fresh air audit

Friday, 14 October 2022


Prepared For David V Unagi Cheetham Hill

18 Issues Identified



ISSUE 1

Assigned To Canopy Hood



ISSUE 2

Assigned To Baffle Filters Removed And Cleaned Daily

Also every 6 month baffle filters and canopy hood deep cleaned with a tr19 certification and report



ISSUE 3

Assigned To Canopy Grease Pot 1 Emptied And Cleaned Daily



ISSUE 4

Assigned To Grease Pot 2 Cleaned Daily




ISSUE 5

Assigned To Fresh Air Wall Plate Fan and Speed Controller



ISSUE 6

Assigned To Gas Interlock Panel What Arrows Are Pointing At
In square extract fan speed controller



ISSUE 7

Assigned To Gas Solinoid



ISSUE 8

Assigned To Extract Exhaust 500 Dia



ISSUE 9


Assigned To Flak Woods 500 Maxi Fan



ISSUE 10

Assigned To Inspection Hatches

To deep clean below and above fan motor and duct work every 6 months to a tr19 certification and report



ISSUE 14

Assigned To Cleaning Hatch

To deep clean below and above fan motor and duct work every 6 months to a tr19 certification and report



ISSUE 15

Assigned To Fresh Air External Louvre

Fresh air Louvre is 4 meters lower than the top of the high velocity cowl what air stream's discharges a further 4 meter plus extracted air from canopy hood and kitchen



ISSUE 16

Assigned To Extract Exhaust To Nearest Building With White Gable 20meters

And extract to other building is 30meters plus
These 2 buildings are offices only



ISSUE 18

Assigned To Adjacent Office Building Is Over 40 Meters Away




ISSUE 19

Assigned To This Office Building Is Over 40 Meters Away




ISSUE 16 (1)

Assigned To Nearest Living Apartments Over 50 Meters Away
From Exhaust And All Office Building All 30 Meters Plus Away
From Exhaust



ISSUE 17

Assigned To Gas Cert



ISSUE 18 (1)

Assigned To Gas Cert